Checklist for the recommended repair process

Complaint RCEPS EML „steering feels sticky/ is to soft/ to heavy/ to imprecise"

Campaign 48K8/48L1 performed? — no → 1.Test Drive / 2.Perform campaign 48K8/48L1

yes ↓

1.Test Drive
2.Notice a difference to the first TD?

↓

Steering still feels unusual? — no → **Return to customer**

yes ↓

1.Check the quality and condition of the wheels and tres.
2.Check chassis-parts for damage.
3.Check the universal-joint of the intermediate steering shaft for stiffness.
4.Any entrys in the diagnostic-file?

↓

All parts are okay? — no → 1.Compare, adjust or repair / 2.Test Drive

yes ↓

Check the Software Version in ECU-adress 44

↓

SW-Version
B8/Q5 = 0511
C7/D4 = 0013 — no → Perform SVM-Code 44A009

yes ↓

1.diagnosis → adress 44 → self-diagnosis → basic setting
→ **perform Relayfunctiontest** → start → Log In Code 20103
2.Test Drive

↓

Steering still feels unusual? — yes →

no ↓

Return to customer

Audi
Vorsprung durch Technik