

Log-GFU-834-348489
P0507 - 35-00 - Higher than Expected.
18010 - Power Supply Terminal 30
P1602 - 35-00 - Voltage too Low

Readiness: 0000 0001

Address 03: ABS Brakes
Control Module Part Number: 4B0 614 517 G
Component and/or Version: ABS/ESP front
Software Coding: 06499
Work Shop Code: WSC 02334
VCID: A502BDC73D6DAF620E-51CE
1 Fault Found:

01421 - High Pressure Switch Valve 2 for Electronic Stability Program (N228)
35-00 - -