

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: Release 22.3.1(x64) Data version: 20220407 DS337.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473
Mileage: 376230km-233778mi Repair Order: 18.5.2022

Chassis Type: 8K-AU48 (8R0)
Scan: 01 02 03 05 08 09 13 15 16 17 18 19 20 42 44 46 47 52 53 56
5C 5F 62 69 72

VIN: WAUZZZ8K5DA209111 Mileage: 376230km-233778miles

01-Engine -- Status: Malfunction 0010
02-Auto Trans -- Status: Malfunction 0010
03-ABS Brakes -- Status: Cannot be reached 1100
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: Malfunction 0010
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: Malfunction 0010
13-Auto Dist. Reg -- Status: Malfunction 0010
15-Airbags -- Status: Malfunction 0010
16-Steering wheel -- Status: Malfunction 0010
17-Instruments -- Status: Malfunction 0010
18-Aux. Heat -- Status: OK 0000
19-CAN Gateway -- Status: Malfunction 0010
20-High Beam Assist. -- Status: Malfunction 0010
42-Door Elect, Driver -- Status: OK 0000
44-Steering Assist -- Status: Malfunction 0010
46-Central Conv. -- Status: Malfunction 0010
47-Sound System -- Status: Malfunction 0010
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: Malfunction 0010
56-Radio -- Status: Malfunction 0010
5C-Lane Maintain. -- Status: Malfunction 0010
5F-Information Electr. -- Status: Malfunction 0010
62-Door, Rear Left -- Status: OK 0000
69-Trailer -- Status: Malfunction 0010
72-Door, Rear Right -- Status: OK 0000

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 2

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 01: Engine (J623-CDUC) Labels: 059-907-401-V2.clb
Part No SW: 8K5 907 401 G HW: 4G0 907 401
Component: 3.0TDI EDC17 X40 0001
Revision: 53X40--- CVN: E8651BA8
Coding: 1225401A057603020000
Shop #: WSC 06325 000 00000
ASAM Dataset: EV_ECM30TDI0118K5907401G 001001
ROD: EV_ECM30TDI0118K5907311A.rod
VCID: 3467DC359F4A462F1B-8060
VINID: 9D196AAAA21B1544420090410425E15738

3 Faults Found:

14587 - Cylinder 5 Glow Plug Circuit (Q14)

P0675 00 [039] - Electrical Fault

Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 2

Fault Frequency: 1

Mileage: 376234 km

Date: 2022.05.18

Time: 16:04:39

Engine RPM: 0.00 /min

Normed load value: 0.0 %

Vehicle speed: 255 km/h

Coolant temperature: 19 °C

Intake air temperature: 21 °C

Ambient air pressure: 1010 mbar

Voltage terminal 30: 11.160 V

Unlearning counter according OBD: 40

Glow-control unit: activation voltage: 10880 mV

Glow_period_control_unit_ground_offset_voltage: -160 mV

Glow-control unit: calculated glow voltage: 11385 mV

Glow_period_control_unit_energy_integrator_calculated_value: 125.8 V²s

Glow cycles upon reaching temperature threshold-Bits 0-7: 0

Glow cycles upon reaching temperature threshold-Bits 0-7: 22

Glow status-Bits 0-7: 0

Glow status-Bits 0-7: 0

Co EOM st Op Mode Short-Bits 0-7: 8

7136 - No Communication with ABS Brake Control Module

U0121 00 [039] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Mileage: 376234 km

Date: 2022.05.18

Time: 13:10:03

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 3

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Engine RPM: 0.00 /min
Normed load value: 0.0 %
Vehicle speed: 255 km/h
Coolant temperature: 18 °C
Intake air temperature: 19 °C
Ambient air pressure: 1010 mbar
Voltage terminal 30: 11.840 V
Unlearning counter according OBD: 40
Limitation: accelerator pedal: 0.0 Nm
CAN status - engine control module-Bits 0-7: 0
Cruise Control System (CCS): status-Bits 0-7: 244
CAN status - transmission control module-Bits 0-7: 0
CAN status - brake control module 1-Bits 0-7: 0
CAN status - brake control module 2-Bits 0-7: 0
selected gear-Bits 0-7: 0

4713 - No Communication with ABS Brake Control Module

U0121 00 [167] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001
Fault Priority: 2
Fault Frequency: 1
Mileage: 376234 km
Date: 2022.05.18
Time: 13:10:03

Engine RPM: 0.00 /min
Normed load value: 0.0 %
Vehicle speed: 0 km/h
Coolant temperature: 18 °C
Intake air temperature: 19 °C
Ambient air pressure: 1010 mbar
Voltage terminal 30: 11.840 V
Unlearning counter according OBD: 40
Limitation: accelerator pedal: 0.0 Nm
CAN status - engine control module-Bits 0-7: 0
Cruise Control System (CCS): status-Bits 0-7: 244
CAN status - transmission control module-Bits 0-7: 0
CAN status - brake control module 1-Bits 0-7: 0
CAN status - brake control module 2-Bits 0-7: 0
selected gear-Bits 0-7: 0

Readiness: 0 0 0 0 X

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 02: Auto Trans (J217) Labels:| 0B5-927-156.clb
Part No SW: 8K2 927 156 J HW: 0B5 927 156 J
Component: 0B5 30 TDIRdW H01 0005
Revision: --H01--- CVN: 00006E53
Coding: 000001
Shop #: WSC 06335 000 00000
ASAM Dataset: EV_TCMDL501021 001012
ROD: EV_TCMDL501021.rod
VCID: 3D71F911AC008767E4-8068

1 Fault Found:

18148 - No Communication with ABS Brake Control Module

U0121 00 [039] - -

Not Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 40

Mileage: 376234 km

Date: 2022.05.18

Time: 13:10:02

Engine RPM: 0 /min

Transmission input speed: 0 /min

Transmission output speed: 2000 /min

Engine torque: -68 Nm

ATF temperature: 17 °C

Accelerator pedal position: 0.0 %

Clutch status: Beide Kupplungen offen

Unlearning counter according OBD: 40

Voltage terminal 30: 12.000 V

Voltage_5V_CAN_pressuresensors-Param to DOP: 4.910 V

Address 03: ABS Brakes

Cannot be reached

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 05: Acc/Start Auth. (J393) Labels: 8K0-907-064-05.clb
Part No SW: 8K0 907 064 GF HW: 8K0 907 064 FF
Component: BCM2 2.0 H12 0633
Revision: 00002001
Coding: 05A24040000000000000
Shop #: WSC 06335 000 00000
VCID: 7AFB320DF5AE705F81-802E

Subsystem 1 - Part No SW: 8K0 959 754 D HW: 8K0 959 754 D
Component: FBSAUDIB8 IDG H71 0083
Serial number: 0513000004716014

1 Fault Found:

01330 - Central Control Module for Central Convenience (J393)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:02

Address 08: Auto HVAC (J255) Labels: Redir Fail!
Part No SW: 8K1 820 043 R HW: 8K1 820 043 R
Component: KLIMA 1 ZONE H02 0123
Revision: A1000000 Serial number: 01080220131873
Coding: 3628008000
Shop #: WSC 06335 000 00000
VCID: 377DEB39863CAD373E-8062

1 Fault Found:

01316 - ABS Control Module

008 - Implausible Signal

Freeze Frame:

Fault Status: 01101000

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:02

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 6

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 09: Cent. Elect. (J519) Labels: 8K0-907-063.clb
Part No SW: 8K0 907 063 DJ HW: 8K0 907 063 DJ
Component: BCM1 1.0 H16 0103
Revision: 09016001 Serial number: 00000552750902
Coding: 260000108074AFC00081400300001D0D0F1C670826090201000004004401010200020024000000
Shop #: WSC 06335 000 00000
VCID: 7AFB320DF5AE705F81-802E

Subsystem 1 - Part No SW: 8K1 955 119 A HW: 8T1 955 119 Labels: 1KX-955-119.CLB
Component: WWS 120213 H07 0080
Serial number: SWF13020125958
Coding: 00FD11

Subsystem 2 - Part No SW: 8U0 955 559 B HW: 8U0 955 559 B Labels: 8U0-955-559.CLB
Component: G397_RLFS H06 0002
Serial number: 20983212
Coding: 02005D

Subsystem 3 - Part No SW: 8K0 941 531 AS HW: 8K0 941 531 AS
Component: E1 - LDS H03 0031
Serial number: 000000000000702131130

Subsystem 4 - Part No SW: 8K5 941 329 HW: 8K5 941 329
H01 0031

Subsystem 5 - Part No SW: 4G0 907 658 A HW: 4G0 907 658 A
Component: Humidity_Sens H03 0002
Serial number: 9D080F860000000000001

3 Faults Found:

02233 - Left Headlight Power Output Stage (J667)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:02

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 7

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Time: 13:10:03

02658 - Power Output Stage for Left Headlight (J667); Incorrectly Coded
000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 3

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 16:04:38

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 8

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 13: Auto Dist. Reg (J428) Labels: None
Part No SW: 8K0 907 561 B HW: 8K0 907 561 B
Component: ACC3 H11 0100
Serial number: 000000000000000
Coding: 007DA1
Shop #: WSC 06335 000 00000
VCID: 3169D5216858730770-8064

3 Faults Found:

00473 - Control Module for Elect. Park/Hand Brake (J540)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101
Fault Priority: 6
Fault Frequency: 2
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:02

Freeze Frame:

Temperature: 25.0°C
Voltage: 11.78 V
Hex Value: 0x00C5
Speed: 0.0 km/h
Lateral Accel.: 0.00 m/s²

01314 - Engine Control Module

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:02

Freeze Frame:

Temperature: 25.0°C
Voltage: 11.78 V
Hex Value: 0x00BE
Speed: 0.0 km/h
Lateral Accel.: 0.00 m/s²

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100
Fault Priority: 6

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 9

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:03

Freeze Frame:
Temperature: 25.0°C
Voltage: 11.78 V
Hex Value: 0x007A
Speed: 0.0 km/h
Lateral Accel.: 0.00 m/s²

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 10

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 15: Airbags (J234) Labels:| 8K0-959-655.clb
Part No SW: 8K0 959 655 N HW: 8K0 959 655 N
Component: AirbagVW-AU10 H45 0610
Serial number: 003KFD9893A4
Coding: 30514435363030303030554A304C384B3053
Shop #: WSC 48914 001 1048576
ASAM Dataset: EV_AirbaECUVWAUDI010 003010
ROD: EV_AirbaECUVWAUDI010_003_AU48.rod
VCID: 489F98C5F3C2D2CF47-801C

Crash sensor for side airbag: driver side:
Serial number: 6334MSME7415286CI

Front Passenger's Side Airbag Crash Sensor:
Serial number: 6344MSME7865552FR

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 6352QSME3F2C457E\$

Passenger side rear thorax airbag crash sensor:
Serial number: 6362QSME402C1B7AP

Crash sensor for front airbag: driver side:
Serial number: 63732SME3D2C195AB

Crash sensor for front airbag: front passenger side:
Serial number: 63832SME1E2B06764

1 Fault Found:

13636864 - Control Module for ABS Brakes

U1015 00 [009] - No Communications

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Date: 2022.05.18

Time: 13:10:03

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 11

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 16: Steering wheel (J527) Labels: 8K0-953-568.clb
Part No SW: 8K0 953 568 M HW: 8K0 953 568 M
Component: Lenks.Modul H03 0005
Revision: ----- Serial number: 90372MBA0004C
Coding: 0000FF
Shop #: WSC 06335 000 00000
VCID: 44878CF5C7EAF6AFAB-8010

Component: E221 - MFL H03 0004

1 Fault Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:02

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 12

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 17: Instruments (J285) Labels: 8T0-920-xxx-17.clb
Part No SW: 8K0 920 931 M HW: 8K0 920 931 M
Component: KOMBIINSTR. H35 0556
Revision: 00300000 Serial number: UVE77CD2E
Coding: 13E611004F010008000000
Shop #: WSC 06335 000 00000
VCID: 387FE8058B22A24F37-806C

2 Faults Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:03

01325 - Control Module for Tire Pressure Monitoring (J502)

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:08

Address 18: Aux. Heat (J364) Labels: 8R0-265-105.clb
Part No SW: 4H0 265 105 E HW: 4H0 265 105 E
Component: Standheizung H24 0260
Revision: 66006006 Serial number: 20130129070855
Coding: 5D2401
Shop #: WSC 06335 000 00000
VCID: 24472C7527AAD6AF8B-8070

No fault code found.

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 13

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 19: CAN Gateway (J533) Labels: 8T0-907-468.clb
Part No SW: 8R0 907 468 P HW: 8R0 907 468 D
Component: GW-BEM 5CAN-M H11 0055
Revision: 1Z100027 Serial number: 2741Z13201801E
Coding: 80CF07FF00
Shop #: WSC 06335 000 00000
VCID: 4C97A4D5EFBA3EEF63-8018

Subsystem 1 - Part No SW: 8T0 915 181 HW: 8T0 915 181
Component: J367-BDMHella H03 8041
Serial number: 4038349101

Subsystem 2 - Part No SW: 8K0 959 663 B HW: 8K0 959 663 B
Component: J532_DCDCStab H05 0006
Serial number: 13040000460021200410

1 Fault Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 2

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:03

Freeze Frame:

Bin. Bits: 00111

Voltage: 11.90 V

Count: 6

Bin. Bits: 10000

Time: 25.40 s

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 14

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 20: High Beam Assist. (J844) Labels: 8K0-857-511.clb
Part No SW: 8T0 857 511 AD HW: 8T0 857 511 AD
Component: FLA H04 0012
Revision: AA001002
Coding: 02019164747464545425363E00
Shop #: WSC 06335 000 00000
VCID: 7CF73415FF9A4E6F93-8028

1 Fault Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 19

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.13

Time: 12:58:47

Address 42: Door Elect, Driver (J386) Labels: 8K0-959-793.clb
Part No SW: 8K0 959 793 R HW: 8K0 959 793 P
Component: TSG FA H02 0506
Revision: Serial number: 0000051696164
Coding: 011C12205C00410001
Shop #: WSC 06335 000 00000
VCID: 4FADB3D91EAC05F706-801A

No fault code found.

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 44: Steering Assist (J500) Labels: 8K0-909-144.clb
Part No SW: 8K0 909 144 F HW: 8K0 909 144 B
Component: RCEPS H37 0507
Revision: 00001000 Serial number: 0028097964
Coding: 100001000001
Shop #: WSC 06334 000 00000
ASAM Dataset: EV_RCEPSAU48X 008014
ROD: EV_RCEPSAU48X_008.rod
VCID: 3467DC359F4A462F1B-8060

1 Fault Found:

3158273 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 2

Reset counter: 21

Mileage: 376234 km

Date: 2022.05.18

Time: 13:10:02

Write only channel

Address 46: Central Conv. (J393) Labels: 8K0-907-064-46.clb
Part No SW: 8K0 907 064 GF HW: 8K0 907 064 FF
Component: BCM2 2.0 H12 0633
Revision: 00002001 Serial number: 0300320933
Coding: 01000E2020B90081812002368000000F
Shop #: WSC 06335 000 00000
VCID: 7AFB320DF5AE705F81-802E

1 Fault Found:

01316 - ABS Control Module

004 - No Signal/Communication - MIL ON

Freeze Frame:

Fault Status: 11100100

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:02

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 16

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 47: Sound System (J525) Labels: 8T0-035-223-BOM.clb
Part No SW: 8T1 035 223 A HW: 8T1 035 223 A
Component: DSP Prem H05 0030
Revision: 00005001 Serial number: 94813010927802
VCID: 2D51C951746017E754-8078

1 Fault Found:

03278 - Functionality Limited due to Missing Messages

000 - -

Freeze Frame:

Fault Status: 01100000
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:07

Freeze Frame:

Voltage: 11.90 V
Temperature: 31.0°C
Temperature: 35.0°C
Bin. Bits: 00000100
Bin. Bits: 00000100
Bin. Bits: 00000000

Address 52: Door Elect, Pass. (J387) Labels: 8K0-959-792.clb
Part No SW: 8K0 959 792 R HW: 8K0 959 792 P
Component: TSG BF H02 0506
Revision: Serial number: 0000051430945
Coding: 011C12205E00410001
Shop #: WSC 06335 000 00000
VCID: 4E93AEDD19A60CFF0D-801A

No fault code found.

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 53: Parking Brake (----) Labels: 8K0-907-801-V2.clb
Part No SW: 8K0 907 801 L HW: 8K0 907 801 J
Component: EPB-4 H01 0003
Revision: ----- Serial number: 20000000224191
ASAM Dataset: EV_ParkBrake_001027
ROD: EV_ParkBrake_AU48.rod
VCID: 387FE8058322A24F37-806C

4 Faults Found:

328448 - Function Restricted due to Missing Message(s)

U1111 00 [137] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Date: 2022.05.18

Time: 13:10:02

Voltage terminal 30: 11.9 V

Internal Fault ID: 89

Vehicle speed: 510 km/h

Network management state: normal

Function light in parking brake button: OFF

Red operating lamp: OFF

Red warning lamp: OFF

Green operating lamp: OFF

Yellow warning lamp: OFF

Terminal 15 status: On

RWU: not active

DSD: not active

HTR: not active

ECD: not active

ACC requested apply: not active

Auto Adjust: not active

General Inspection Function: not active

Internal Parking Brake state: Emergency running mode

Status of parking brake button: Not operated

Status ParkingBrake left: Open

Status ParkingBrake right: Open

328704 - Function Restricted due to Missing Message(s)

U1111 00 [137] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Reset counter: 21
Mileage: 376234 km
Date: 2022.05.18
Time: 13:10:02

Voltage terminal 30: 11.9 V
Internal Fault ID: 90
Vehicle speed: 510 km/h
Network management state: normal
Function light in parking brake button: OFF
Red operating lamp: OFF
Red warning lamp: OFF
Green operating lamp: OFF
Yellow warning lamp: OFF
Terminal 15 status: On
RWU: not active
DSD: not active
HTR: not active
ECD: not active
ACC requested apply: not active
Auto Adjust: not active
General Inspection Function: not active
Internal Parking Brake state: Emergency running mode
Status of parking brake button: Not operated
Status ParkingBrake left: Open
Status ParkingBrake right: Open

328960 - Function Restricted due to Missing Message(s)

U1111 00 [137] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Date: 2022.05.18
Time: 13:10:02

Voltage terminal 30: 11.9 V
Internal Fault ID: 91
Vehicle speed: 510 km/h
Network management state: normal
Function light in parking brake button: OFF
Red operating lamp: OFF
Red warning lamp: OFF
Green operating lamp: OFF
Yellow warning lamp: OFF
Terminal 15 status: On
RWU: not active
DSD: not active

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

HTR: not active
ECD: not active
ACC requested apply: not active
Auto Adjust: not active
General Inspection Function: not active
Internal Parking Brake state: Emergency running mode
Status of parking brake button: Not operated
Status ParkingBrake left: Open
Status ParkingBrake right: Open

329216 - Function Restricted due to Missing Message(s)

U1111 00 [137] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

MIL ON - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Date: 2022.05.18
Time: 13:10:02

Voltage terminal 30: 11.9 V
Internal Fault ID: 92
Vehicle speed: 510 km/h
Network management state: normal
Function light in parking brake button: OFF
Red operating lamp: OFF
Red warning lamp: OFF
Green operating lamp: OFF
Yellow warning lamp: OFF
Terminal 15 status: On
RWU: not active
DSD: not active
HTR: not active
ECD: not active
ACC requested apply: not active
Auto Adjust: not active
General Inspection Function: not active
Internal Parking Brake state: Emergency running mode
Status of parking brake button: Not operated
Status ParkingBrake left: Open
Status ParkingBrake right: Open

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 20

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 56: Radio (R) Labels: 4F0-035-0xx-56.clb
Part No SW: 4G1 035 053 G HW: 4G1 035 053
Component: Radio U Basic H41 0121
Revision: AB001007 Serial number: 227B40D7693677
Coding: 010003010000000001
Shop #: WSC 06335 000 00000
VCID: 23452F6922A4D197F2-8076

1 Fault Found:

03278 - Functionality Limited due to Missing Messages

000 - -

Freeze Frame:

Fault Status: 01100000

Fault Priority: 6

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:06

Freeze Frame:

Bin. Bits: 00000000 00000100

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 21

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 5C: Lane Maintain. Labels: None
Part No SW: 8T0 907 217 A HW: 4E0 907 217 C
Component: J759 HC 0040
Revision: 00H08006 Serial number: 6002132150013C
Coding: 0102001
Shop #: WSC 06335 000 00000
VCID: 377DEB39463CAD373E-8062

2 Faults Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:02

01309 - Power Steering Control Module (J500)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101
Fault Priority: 6
Fault Frequency: 1
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:02

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 22

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 5F: Information Electr. (J794) Labels: 4E0-035-6xx-5F.clb
Part No SW: 8R1 035 670 G HW: 8R1 035 670 C
Component: H-BNT-EU H45 0661
Revision: ----- Serial number: 207B.0D7537609
Coding: 0F0100010006ABED2980EB5E00000403040000000000000000
Shop #: WSC 06335 000 00000
VCID: 377DEB39863CAD373E-8062

Subsystem 1 - Part No: 8R0 060 884 AR
Component: ECE 2013 1505

Subsystem 2 - Part No SW: 8R0 919 604 A HW: 8R0 919 604 A
Component: DU7 High H42 0104
Serial number: A130BQ0D2654374

Subsystem 3 - Part No SW: 8T0 919 611 L HW: 8T0 919 611 C
Component: E0380 Bedient H02 0030
Serial number: 00000001410296

Subsystem 4 - Part No: 8R0 060 961 E
Component: CD-Database 4949

3 Faults Found:

03157 - Functionality limited due to Communications Disruption

000 - - - Intermittent

Freeze Frame:

Fault Status: 00100000

Fault Priority: 6

Fault Frequency: 1

Reset counter: 61

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

Time: 13:10:07

Freeze Frame:

Bin. Bits: 00000000 10000000

Bin. Bits: 00000000 00000000

Bin. Bits: 00000000 00000000

Bin. Bits: 00000000 00000000

Bin. Bits: 00000000 00000000

00862 - Antenna for GPS Navigation (R50/R52)

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 21

Mileage: 376234 km

Time Indication: 0

Date: 2022.05.18

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 23

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Time: 13:10:15

Freeze Frame:
Voltage: 11.80 V

03278 - Functionality Limited due to Missing Messages

000 - -

Freeze Frame:
Fault Status: 01100000
Fault Priority: 6
Fault Frequency: 4
Reset counter: 21
Mileage: 376234 km
Time Indication: 0
Date: 2022.05.18
Time: 13:10:10

Freeze Frame:
Bin. Bits: 00000110 01100000
Bin. Bits: 00000000 00000000

Address 62: Door, Rear Left (J388) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 G HW: 8K0 959 795 D
Component: TSG HL H01 0506
Revision: Serial number: 0000051497045
Coding: 010C12204000210001
Shop #: WSC 06335 000 00000
VCID: 468396FDF1D6C4BFB5-8012

No fault code found.

VCDS
Self-Diagnosis Log
Wednesday, 18, May, 2022, 16:12:51:28969
Page 24

VIN: WAUZZZ8K5DA209111 License Plate: ZLJ-473

Address 69: Trailer (J345) Labels: 8K0-907-383.clb
Part No SW: 8K0 907 383 E HW: 8K0 907 383 E
Component: Anhaenger H09 0100
Revision: 1A001001 Serial number: 00000192276636
Coding: 010D000000000000
Shop #: WSC 25397 000 00000
VCID: 3663E63D8136543F25-8062

1 Fault Found:

01316 - ABS Control Module

004 - No Signal/Communication

Freeze Frame:

Fault Status: 01100100

Fault Priority: 6

Fault Frequency: 4

Reset counter: 17

Mileage: 375802 km

Time Indication: 0

Date: 2022.04.26

Time: 17:41:53

Address 72: Door, Rear Right (J389) Labels: 8K0-959-795.clb
Part No SW: 8K0 959 795 G HW: 8K0 959 795 D
Component: TSG HR H01 0506
Revision: Serial number: 0000051496712
Coding: 010C12204000210001
Shop #: WSC 06335 000 00000
VCID: 468396FDF1D6C4BFB5-8012

No fault code found.

End----- (Elapsed Time: 03:59)-----